



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name	Eastern Illinois University			System ID Number:	IL0295500		Current Inventory Date:	3/19/24		
*Please enter totals in the empty box next to each category	Total Service lines:	26	Total Lead:	0	Total Non-Lead:	0	Total Galvanized Requiring replacement:	0	Total Unknown:	0	Website link to Material Inventory:

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2111 9th st Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	C	C	NL	N						
1602 9th st Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	Plastic - PVC, HDPE, PEX (P)		NL	N						
1525 7th st Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	G	G	NL	N						
2010 18th st Charleston II 61920	N/A	N	N	2010	2010	Construction Records	UNL	O	O	NL	N						
2012 18th st charleston II 61920	N/A	N	N	2013	2013	Construction Records	UNL	O	O	NL	N						
1001/1005 Greek Court Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	Plastic - PVC, HDPE, PEX (P)		NL	N						
1000/1004 Greek Court Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	Plastic - PVC, HDPE, PEX (P)		NL	N						
1009/1013 Greek Court Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	Plastic - PVC, HDPE, PEX (P)		NL	N						
1008/1012 Greek Court Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	Plastic - PVC, HDPE, PEX (P)		NL	N						
1017/1021 Greek Court Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	Plastic - PVC, HDPE, PEX (P)		NL	N						
1016/1020 Greek Court Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	Plastic - PVC, HDPE, PEX (P)		NL	N						
1050/1051 Greek Court Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
1030/1034 Greek Court Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
2103 12th st Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
975 Edgar st Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
280 Grant St Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
408 West Hayes Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
1 Grant st Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
1536 4th st Charleston II	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	G	G	NL	N						
1967 4th st Charleston II 61920	N/A	N	N	2021	2021	Construction Records	UNL	O	O	NL	N						
501 Roosevelt dr Charleston II 61920	N/A	N	N	2015	2015	Construction Records	UNL	O	O	NL	N						
151 Terrace Lane Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
2207 9th st Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
1600 7th st Charleston II 61920	N/A	N	N	Unkown	Unkown	Visual Inspection	UNL	O	O	NL	N						
2150 7th st Charleston II 61920	N/A	N	N	2018	2018	Construction Records	UNL	Plastic - PVC, HDPE, PEX (P)		NL	N						
408 W Hayes Charleston II 61920	N/A	N	N	2013	2013	Construction Records	UNL	O	O	NL	N						